



DIKAMAR® TRACE SOFT TOE

COLORS: Black | Black

SIZES: US 7>13

SAFETY LEVEL: Soft Toe

Item no. 95005BK

- Application: Agriculture
- Lightweight and flexible.
- Abrasion-resistant for longer life.
- 100% waterproof.
- Thermal insulation down to -40°C/-40°F.
- PU removable insole with carbon active, breathable and antibacterial.
- ASTM F2413-18.
- Certified by the European standard EN ISO 20347:2022 O4+CI+SR.
- Up to 30% lighter than PVC and rubber safety boots and last longer.



CLEANING INSTRUCTIONS

Cleaning can be done by washing your boots, after each use, with a soft brush and mild detergent. Rinse away the remains of the detergent with water and allow the boot to dry at room temperature and in the shade. Store in a well-ventilated and dry place. Regular cleaning and replacement of the insole, when used, is also important to prevent the proliferation of bacteria. Careful and regular cleaning increases the durability of your wellingtons. When replacing the insole you must ensure that you are using an insole just like the original.

